

Notice



- ☐ CORRECTION
 ☒ PRODUCTION CHANGE
☐ SERVICE FLASH
 ☐ ADD INFORMATION

FILE NO.

REVISION 0

Please add this notice to the Service Manual listed below.

Category: **COLOR TELEVISION** Date: **APRIL / 12 / 2011**
 Model: **DP26640** Effective from : Chassis No. **P26640-07**
 Destination: **U.S.A. / CANADA** REF : **No. SM780181-06**

NOTE: Match the Chassis No. on the unit's back cover with the Chassis No. in the Service Manual. **If the Service Manual Chassis No. does not match the unit's**, additional Service Literature is required. This chassis is similar to Chassis No. P26640-06. Only the **difference** Service Information is given in this manual. For detailed Service Information, refer to the **Original** Service Manual and **Notices** for Chassis No. P26640-06 used in Model DP26640 (SM780181).

SERVICING SHOULD BE PERFORMED BY ONLY TRAINED AND QUALIFIED SERVICE PERSONNEL.

1. IN THE SERVICE ADJUSTMENTS

PAGE 4 ON-SCREEN SERVICE MENU

Item No. **088 OP2 Data** should be **02h** in the table and in Note 2.

2. IN THE CHASSIS ELECTRICAL PARTS LIST MISCELLANEOUS

The reason for change.

- A : Misprint B : Quality Reliability C : Standardization
 D : Design E : Add as a possible sub F : Schematic location change
 G : Purchasing Request

Page & Section	Schematic Location		Part No.	Description	Q'ty	Interchangeability	Reason
Page 18, Chassis Electrical Parts List	EL901	Old	1AV4T40C17000	LCD(M260TWR1 R1)	1	NO	D
		New	1AV4T40C05300	LCD(LC260WXN-SBA1)	1	NO	
	EL902	Old	1AV4U20C46200	UNIT, INVERTER	1	NO	D
		New	86632L-0550A-	UNIT, INVERTER	1	NO	
	WK5LV-PN	Old	1AA4W30B66500	LVDS CABLE, 40P-31P	1	NO	D
		New	1LB4W30B25200	LVDS CABLE, 40P-31P	1	NO	
	N/A	Old	N8MK T-CON	N8MK T-CON	1	NO	D
		New	86871L-1603A-	Timing Control Board	1	NO	

For parts or service contact:

Sanyo Manufacturing Corporation
P.O. Box 2000
3333 Sanyo Road
Forrest City, Arkansas 72335-2000

April 2011 SMC

Published in Mexico

DP26640, N8ML, PRODUCT CODE 113023504

REFERENCE No. SM780181-07